

# SUPPLEMENTAL TYPE CERTIFICATE

## 10062960 REV. 1

This Supplemental Type Certificate is issued by EASA, acting in accordance with Regulation (EC) No. 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation and in accordance with Commission Regulation (EU) No. 748/2012 to

## ALPINE AEROTECH LP

1260 INDUSTRIAL ROAD WEST KELOWNA BC V1Z 1G5 CANADA

and certifies that the change in the type design for the product listed below with the limitations and conditions specified meets the applicable Type Certification Basis and environmental protection requirements when operated within the conditions and limitations specified below:

Original Type Certificate Number: EASA.IM.R.106

Type Certificate Holder: BELL HELICOPTER TEXTRON, INC.

Type: Bell 212/412 Model: 212/412/412EP

Original STC Number: TCCA STC SH00-2

### **Description of Design Change:**

Firewall Web Installation (Alpine Aerotech Ltd. P/ N AAL-061-903-001).

### **EASA Certification Basis:**

The Certification Basis (CB) for the original product remains applicable to this certificate/ approval. The requirements for environmental protection and the associated certified noise and/ or emissions levels of the original product are unchanged and remain applicable to this certificate/ approval.

#### **Associated Technical Documentation:**

Installation Instructions Document No. 191M-99-003-II, Revision NC, dated November 17, 1998, or later TCCA approved revisions.

See Continuation Sheet(s)

For the European Aviation Safety Agency

Cologne, Germany, 15 September 2017

Pièr Giorgio COLOMBO Medium Rotorcraft Section

Manager





Master Drawing List Document No. D191M-99-003, Rev. NI, dated February 22, 1999, or later TCCA approved revisions.

### **Limitations/Conditions:**

Prior to installation of this design change it must be determined that the interrelationship between this design change and any other previously installed design change and/ or repair will introduce no adverse effect upon the airworthiness of the product.



